



STOP SALE

Release Date: November 17, 2022

IND

Communication #: I-22-06

Model Year(s): 2021-2022

— Confidential and Proprietary —

VERSION: R01 (November 17, 2022)

IMPORTANT STOP SALE NOTICE! **Stop selling affected vehicles immediately.**

SUBJECT: CHIEF AND SCOUT FUEL PUMP

PURPOSE

Indian Motorcycle has determined that some Model Year 2022 Chief and Model Year 2021-2022 Scout motorcycles may experience a failure at the fuel pump during operation. If this occurs, the engine may stall increasing the risk of a crash and serious injury.

Indian Motorcycle is currently evaluating a repair procedure for this concern and will provide an update to dealers in the coming weeks.

AFFECTED MODELS

| MODEL YEAR | MODELS | AFFECTED RANGE |
|------------|--------|---|
| 2022 | Chief | Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to look up affected units. |
| 2021-2022 | Scout | |

CUSTOMER NOTIFICATION

When repair details are available, Indian Motorcycle will notify consumers by letter (and email if available) immediately and follow-up with additional repair plans. At that time, dealers should also contact owners of affected VINs / PINs to inform them of this announcement.

CONTACT POLARIS

If you have questions that are not addressed in this document, contact Indian Motorcycle Service through Ask Polaris or by phone at 800-330-9407 (US/Canada Dealers Only).

DEALER - WHAT TO DO?

As of November 17, 2022, **YOU MUST NOT SELL OR DELIVER** any affected **NEW OR USED Model Year 2021-2022 Scout or 2022 Chief models** affected by this **Stop Sale** until it is repaired according to the **Safety Recall**.